

GLASGOW CENTRAL RAILWAY PHOTOGRAPHS COLLECTION

Item No.	Description
G762/18/1	Unidentified suburban station on Glasgow Central Railway
G762/18/2	Construction on Argyle Street, outside James and John Gray, Hatters, 43 Argyle Street
G762/18/3	A group of boys standing on the pavement, corner of Argyle Street (before construction)
G762/18/4	Tunnelling construction through area of tenements and warehouses, with cut timber in foreground and a group of workers standing in the background [Wellington Court section]
G762/18/5	Tunnelling construction underground showing sand and shovels, bogeys on the track and roof girders
G762/18/6	Close-up of underground roof with metal girders
G762/18/7	Suburban station, possibly Maryhill terminus, with locomotives and goods trains on the tracks, engine sheds to the right and a road with tenements in the background
G762/18/8	Looking along the construction line on a city centre street, with bricks and timber strewn about and workmen digging alongside. A line of tenements and shops can be seen in the background
G762/18/9	View of incomplete underground tunnel showing track and roof with metal girders
G762/18/10	View looking down onto tunnel construction with deep wall alongside and track visible at the bottom. Workmen and tenements viewed on the left.

G762/18/11	Side view of tunnel construction, showing dug-out section with timber shoring, metal girders for roof and bogey on tracks.
G762/18/12	Platform construction, showing pillars and tiled walls. Workmen standing on tracks and uniformed staff on platform.
G762/18/13	As G762/18/12, with time delay,
G762/18/14	Workers and foreman on tunnel construction, showing roof with metal girders, wooden timber lining and bogey on tracks alongside
G762/18/15	Workmen underground, with foremen alongside. Metal roof supports on right with tunnel floor wet and muddy. No track visible.
G762/18/16	Construction work beginning on Argyle Street, outside Wellington Court. Shop fronts and doorways visible and large working crane on roadway beside small wooden shed.
G762/18/17	Close-up of tunnel interior, showing excavator and the sections of metal support lining and rivets (sewer?)
G762/18/18	View from above down into tunnel working, showing timber and metal supports.
G762/18/19	Close-up of figure (foreman) in metal-lined tunnel with water on bottom (sewer?)
G762/18/20	View along Argyle Street with pedestrians, horse and carts and a tram. The timber flooring for the tram lines can be clearly seen. Little evidence of construction work, although there are a number of curious bystanders.
G762/18/21	Extensive construction works around Argyle Street at Oswald Street. Photograph shows roadway completely excavated with machinery, construction workers and onlookers.
G762/18/22	Construction of underground station with bogey on tracks removing rubble.
G762/18/23	Kelvinbridge station interior with view of platforms, track and glass and metal roof. Passengers waiting on platform (same station as G762/18/27)
G762/18/24	View of completed underground station showing platform, waiting rooms and station staff standing on platform. Tunnel visible in background.

G762/18/25	Four construction workers seated inside a small tunnel which is supported by a metal roof (sewer?)
G762/18/26	View above extensive construction works around Argyle Street (?). Photograph shows roadway completely excavated and construction workers. Tenements in background.
G762/18/27	Kelvinbridge station interior with view of platforms, track and glass and metal roof. Passengers waiting on platform (same station as G762/18/23)
G762/18/28	Extensive construction works around shops and tenements Argyle Street. Photograph shows roadway completely excavated with steam machinery, tram lines, several construction workers and a number of onlookers.
G762/18/29	View of bogeys carrying rubble on the tracks in underground workings.
G762/18/30	Open air view of underground workings showing large supporting pillars, rubble and machinery – possibly station construction.
G762/18/31	Extensive construction works around shops and tenements Argyle Street. Photograph shows roadway completely excavated with cranes, huge metal girders, several construction workers and a number of onlookers.
G762/18/32	Open air view of underground construction work, showing timber supports and large metal supporting pillars. Two construction workers and two managers, dressed in suits, one is named as 'Grant'.
G762/18/33	Exterior view of Kelvinbridge Station, with figures in front of the entrance.
G762/18/34	Open air view of underground construction work, showing metal supporting beams and timbers. Several construction workers standing with shovels and two foremen on the left.
G762/18/35	Underground station (Central?) construction showing metal supports being lifted into place by a crane. A number of foremen and construction workers standing on platform.
G762/18/36	Close up of four coats hanging on pages on brick wall, close to construction work.
G762/18/37	View of cobbled roadway with tramlines, with young man leaning on wooden fence in the background. Tenements visible in far distance.
G762/18/38	Entrance to Caledonian Railway, Central Low Level Station. A number of men can be seen standing on the pavement outside. Timetables for Rutherglen to Maryhill are attached to the wall beside the station entrance.
G762/18/39	Entrance to underground workings
G762/18/40	View looking down on underground workings, with crane in background. Workmen standing looking down onto the scene.

G762/18/41	Large excavated shaft on Argyle Street (?)with several onlookers standing at wooden fence overlooking the scene.
G762/18/42	View along Argyle Street showing metal support beams lifted into place. Crane in background.
G762/18/43	View along underground track workings, with large bogey in foreground carrying sand. A number of foremen and standing on tracks beyond the bogey and construction workers at the side.
G762/18/44	Underground workings with piles of rubble and sand. A large number of construction workers are standing in the background of the tunnel.
G762/18/45	View of large open-air construction site with large amount of rubble. Street with tenements and shops visible in background on the right.
G762/18/46	View along Argyle Street (?)beside Robert W. Cairns with construction workers in foreground and excavated shaft just visible. Large metal beams across the road with crane behind. Several onlookers. Similar to G762/18/42
G762/18/47	View along a small tunnel which is supported by a metal roof (sewer?)
G762/18/48	View along a small tunnel which is supported by a metal roof (sewer?)
G762/18/49	View of extensive road excavations on Argyle Street at corner of Oswald Street with metal beams lying across the site and two large cranes in place. Construction workers in foreground and the ubiquitous onlookers leaning against a fence.
G762/18/50	Exterior of Botanic Gardens Station.
G762/18/51	View of extensive road excavations on Argyle Street (?), with metal beams lying across the site and a steam crane on the left with a number of foremen standing close by. Construction workers in foreground and a large number of onlookers just visible on the right.
G762/18/52	Station construction with large crane lifting metal beam support into place. A number of construction workers and foremen standing at the scene. Similar to G762/18/35
G762/18/53	View of steam machinery in operation on Argyle Street (in front of Madeira Court) with a large number of onlookers. Shops and tenements clearly visible behind.
G762/18/54	View of underground entrance shaft
G762/18/55	View of extensive road excavations on Argyle Street (close to Madeira Court) with several male bystanders looking down on the scene from behind a wood fence. Shops and tenements can be seen clearly in the background.

G762/18/56	Open air view of construction work showing wall with muddy sections enclosed by timber pile supports.
------------	---